



Schweißschuhe

Welding nozzles




Kehlnaht
A - Schuh




Doppel V-Naht
DV (X) - Schuh



V-Naht
V - Schuh



Ecknaht
E - Schuh



Überlappnaht
U - Schuh



Kehl - Naht									
Plattendicke „s“ in mm	5	8	10	12	15	20	25	30	35
Schweißschuh	A 3,5	A 5,6	A 7	A 8,4	A 10,5	A 14	A 17,5	A 21	A 24,5

Doppel V (X) - Naht									
Plattendicke „s“ in mm	5	8	10	12	15	20	25	30	35
Schweißschuh	X 5	X 8	X 10	X 12	X 15	X 20	X 25	X 30	X 35

V - Naht									
Plattendicke „s“ in mm	5	8	10	12	15	20	25	30	35
Schweißschuh	V 5	V 8	V 10	V 12	V 15	V 20	V 25	V 30	V 35

Eck - Naht									
Plattendicke „s“ in mm	5	8	10	12	15	20	25	30	35
Schweißschuh	E 5	E 8	E 10	E 12	E 15	E 20	E 25	E 30	E 35

Überlapp - Naht									
Plattendicke „s“ in mm	3	5	6	8	10				
Schweißschuh	U 3	U 6	U 6	U 8	U 10				



Typ 1 – 30 x 50mm
 Typ 2 – 40 x 52mm
 Typ 3 – 90 x 70mm

Schweißschuhrohling

PTFE - Block

Alu - Grundplatte